

Certificate of Structural Repair

PRC Repair Specification:
2014:BSF,Reema, 01

Requirements for repair of Reema House

Certificate No. PRC - 0093

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**110 Burke Drive
Thornhill
Southampton
SO19 6EF**



Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House " .

10 August 2020

Contract Completion Date

067

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

09 September 2020

Issue date



PRC Repair Specification:
2014:BSF,Reema, 01
Certificate No. PRC - 0093
Schedule Continued:

Certificate of Structural Repair

Contract premises:

**110 Burke Drive
Thornhill
Southampton
SO19 6EF**

067

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location
N/A	
N/A	

Notes:

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

09 September 2020

Issue date

