

## Certificate of Structural Repair

PRC Repair Specification:  
BSF-Reema-1:2014

Requirements for repair of Reema House

**Certificate No. PRC - 0114**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**27 Burnham Road  
Tadley  
RG26 4QN**



## Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

03 October 2021

Contract Completion Date

086

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

03 November 2021

Issue date



**PRC Repair Specification:**  
**BSF-Reema-1:2014**  
**Certificate No. PRC - 0114**  
**Schedule Continued:**

**Certificate of Structural Repair**

Contract premises:  
**27 Burnham Road**  
**Tadley**  
**RG26 4QN**

**086**  
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

**Notes:**

**Alan Cairns**  
Name, Position

Signature

**Alan Cairns**  
Registered Practitioner Company Name

**03 November 2021**  
Issue date

