

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0118

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**3 Kingsclere Avenue
Southampton
SO19 9LB**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

16 December 2021

Contract Completion Date

089

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

17 December 2021

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0118
Schedule Continued:

Certificate of Structural Repair

Contract premises:
3 Kingsclere Avenue
Southampton
SO19 9LB

089
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns
 Name, Position



Signature

Alan Cairns Associates Ltd
 Registered Practitioner Company Name

17 December 2021
 Issue date

