

Certificate of Structural Repair

PRC Repair Specification:
BSF_RS_Airey:2017

Requirements for repair of Airey House

Certificate No. PRC - 0124

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**31 Maple Avenue
Bishopthorpe
York
YO23 2RG**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF_RS_Airey:2017 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF_RS_Airey:2017: "Requirements for repair of Airey House".

15 January 2022

Contract Completion Date

098

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

01 February 2022

Issue date



PRC Repair Specification:
BSF_RS_Airey:2017
Certificate No. PRC - 0124
Schedule Continued:

Certificate of Structural Repair

Contract premises:
31 Maple Avenue
Bishopthorpe
York
YO23 2RG

098
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF_RS_Airey:2017, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns
Name, Position



Signature

Alan Cairns Associates Ltd
Registered Practitioner Company Name

01 February 2022
Issue date

