

## Certificate of Structural Repair

PRC Repair Specification:  
BSF-Reema-1:2014

Requirements for repair of Reema House

**Certificate No. PRC - 0122**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**25 Cadland Park  
Holbury  
Southampton  
SO45 2PE**



## Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

11 January 2022

Contract Completion Date

099

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

19 January 2022

Issue date



**PRC Repair Specification:**  
**BSF-Reema-1:2014**  
**Certificate No. PRC - 0122**  
**Schedule Continued:**

**Certificate of Structural Repair**

Contract premises:  
**25 Cadland Park**  
**Holbury**  
**Southampton**  
**SO45 2PE**

**099**  
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

**Notes:**

**Alan Cairns**  
 Name, Position



Signature

**Alan Cairns Associates Ltd**  
 Registered Practitioner Company Name

**19 January 2022**  
 Issue date

