

Certificate of Structural Repair

PRC Repair Specification:
2014: BSF, Reema, 01

Requirements for repair of Reema House

Certificate No. PRC - 0090

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**54 Chambers Avenue,
Romsey,
SO51 5BE**



Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014: BSF, Reema, 01 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification 2014: BSF, Reema, 01: "Requirements for repair of Reema House".

23 September 2020

Contract Completion Date

064

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

12 October 2020

Issue date



PRC Repair Specification:
2014: BSF, Reema, 01
Certificate No. PRC - 0090
Schedule Continued:

Certificate of Structural Repair

Contract premises:
**54 Chambers Avenue,
Romsey,
SO51 5BE**

064
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014: BSF, Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location
N/A	
N/A	

Notes:
Click here to enter text.

Alan Cairns
Name, Position

Signature

Alan Cairns
Registered Practitioner Company Name

12 October 2020
Issue date

